

Dry-dock report

Vessel: ASTRA

IMO: 8878192

Date: 6 May – 29 June 2017

Shipyard: Kållandsö Varv

Kållandsö Sweden





PHOTO REPORT -




Indocking.



Indocking.







Condition of exterior hull after HP wash.




PHOTO REPORT -



Condition of exterior hull after HP wash.



Condition of exterior hull after HP wash.



Example of surface preparation spotbalsting.



PHOTO REPORT -



Example of surface preparation spotbalsting.



Exampel of first T/U exterior hull.



Exampel of spotblasting superstructure.



PHOTO REPORT - Astra Dry-Dock 6 april - 27 may



Exampel of spotblasting superstructure.





Paintwork in progress.





Exampel of touch up areas followed by stripe coat.



PHOTO REPORT - Astra Dry-Dock 6 april - 27 may





Paintwork in progress overview.





Superstructure paintwork in progress.

Photo No. 15



Final full coat at topsides and superstructure.



PHOTO REPORT - Astra Dry-Dock 6 april - 27 may



Full coat of antifouling compleated.



Mast blasting and painting compleated. Mast only mineralbased blasted.



Final full coat of exterior decks and bulwark interior.



PHOTO REPORT - Astra Dry-Dock 6 april - 27 may
Photo No. 19



Final full coatexterior deck aft completed.



Final full coat exterior deck forward completed.





Paintwork completed.